**A. Clear mines from littoral area *(Operational Capability)***

Note: *Quality measures must be assigned in order to assess the acceptability of the operational and enabling capabilities/systems*

1. Plan the clearance effort (1st level enabling capability)
    a. Obtain necessary intelligence information *(2nd level enabling capability)*
        1) Navigation Information (charts, tides and currents, etc)
        2) Enemy maritime mining capability *(3rd level capabilities)*
        3) Weather information
        4) Enemy coastal defense capability
    b. Collaborate with off board nodes (2ndt level enabling capability)
    *Insert 3rd and succeeding levels of enabling capability*
2. Search for/locate the mines
    *Insert 2nd and succeeding levels of supporting capability*
3. Disable/remove/destroy the mine
    *Insert 2nd and succeeding levels of supporting capability*
4. Share the results of the clearance effort
    *Insert 2nd and succeeding levels of supporting capability*
5. Receive logistic support.
    *Insert 2nd and succeeding levels of supporting capability*